

HOW TO RELEASE LINER FROM

HSMF TIMs

- Step 1** Cut pieces of tape as needed
- Step 2** Place tape on HSMF and press down to secure
- Step 3** Peel off tape, removing liner from material
- Step 4** Place side with liner removed face down on metal and press down to secure
- Step 5** Place tape on face-up side of HSMF
- Step 6** Peel off tape in the same fashion as before, removing liner
- Step 7** Place second piece of metal on the face-up side of the HSMF and press down to secure

Contact our engineers: askus@indium.com

Learn more:

www.indium.com/HSMF-liner

ISO 9001
REGISTERED

Form No. 99654 R0
©2019 Indium Corporation



HOW TO RELEASE LINER FROM HSMF TIMs

➔ Remove and Discard

One-Sided HSMF-OS



Release Liner (Remove)
Thermal Compound
Aluminum Foil


➔ Remove and Discard

Two-Sided HSMF



Release Liner (Remove)
Thermal Compound
Aluminum Foil
Thermal Compound
Release Liner (Remove)

➔ Remove and Discard



HSMF Traits:

- Inherent adhesive property
- Cleans up with IPA
- Can be stacked multiple times

Contact our engineers: askus@indium.com

Learn more:

www.indium.com/HSMF-liner

ISO 9001
REGISTERED

Form No. 99654 R0
©2019 Indium Corporation

